

Title:	RN TurboHD DVR Firmware Release Notes	Version:	v3.4.88	Date:	180228
Product:	-F/N Series TurboHD DVRs	Build:		Page:	1 of
Action Required:	None, Information Only				

■ Summary

Release notes for -F/N Series Turbo HD DVRs.

Main update

■ Modified Functions

- Fixed the issue that the serial numbers of some IPCs display abnormally on the IPC list.
- Fixed the issue that the heat map information of IP channel displays abnormally on DS-73/81/9000HUHI-Fx/N Series DVRs.
- Fixed the issue that a large number of searches on the Web leads to the device crashing.

■ Related Product List

-F/N Series TurboHD DVRs	DS-7204HUHI-F1/N DS-7208HUHI-F2/N DS-7216HUHI-F2/N DS-7308HUHI-F4/N DS-7316HUHI-F4/N DS-7108HQHI-F1/N DS-7104HQHI-F1/N DS-9008HUHI-F8/N DS-9016HUHI-F8/N
-----------------------------	--

■ Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance and will take effect automatically after upgrading from previous versions.

We are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

■ NOTES

- Hikvision has all rights to alter, modify, and/or cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special models' change details, please contact our local technical support team.