

<b>Title:</b>	RN DS-76xxNI-E1(E2)P 050217NA	<b>Version:</b>	v3.4.5	<b>Date:</b>	050217
<b>Product:</b>	DS-76xxNI-E1(E2)P Series NVRs	<b>Build:</b>		<b>Page:</b>	1 of 2
<b>Action Required:</b>	None, Information Only				

■ **Summary**

Firmware v3.4.5 has been released for DS-76xxNI-E1(E2)P Series NVRs.

■ **NVR Models Affected**

DS-7604NI-E1/4P	DS-7608NI-E2/8P	DS-7616NI-E2/16P
-----------------	-----------------	------------------

■ **Compatible IP Camera Information**

IP Camera Model	IP Camera Firmware
2xx2 Series	v5.4.0_160530
40xx,41xx,42xx,43xx,6412FWD Series	v5.4.0_160419
1x02,2xx0,2X14 Series	v5.4.3_160705
4026FWD,6026FHWD,iDS-6xxx Series	v5.4.0_160414
4xx5 Series	v5.4.0_160419
2x22FWD, 2x42FWD Series	v5.4.1_160525
R3 platform DF Series	v5.4.0_160613
R4 platform DF Series	v5.4.0_160613
DE Series	v5.3.9_150910
DS-2CD2942F-IS (Fisheye)	v5.4.0_160926
DS-2CD6412FWD-C2	v5.3.9_160315
DS-2CD63xxF (Fisheye)	v5.4.14_160427

■ **New Features**

• **Hik-Connect**

- Added DDNS feature. After having successfully registered the device on Hik-Connect platform, you can access your device via Web browser or client software with the Device Domain.
- Optimized Hik-Connect feature so that when enabled, the Service Terms interface pops up and the checkbox must be checked before the feature is enabled, also, the verification code must contain 6 to 12 letters or numbers and is case sensitive.

**NOTES:** Hik-Connect is disabled by default.

Can't use SADP and the batch configuration tool to enable and disable the Hik-Connect feature. It will be supported in later FW.

The iVMS-4200 in CD does not support the new Hik-Connect features.

<b>Title:</b>	RN DS-76xxNI-E1(E2)P 050217NA	<b>Version:</b>	v3.4.5	<b>Date:</b>	050217
<b>Product:</b>	DS-76xxNI-E1(E2)P Series NVRs	<b>Build:</b>		<b>Page:</b>	2 of 2
<b>Action Required:</b>	None, Information Only				

- **UPnP** – UPnP is disabled by default.

■ **Removed**

- **DDNS** – Removed HiDDNS and IP Server features from the DDNS interface.

■ **Optimized**

- **RTSP** – Optimized RTSP Security issues that allowed a way to retrieve a stream through RTSP without a user name and password.