

<b>Title:</b>	RN DS-76xxNI-E1(E2)P Series NVRs	<b>Versions:</b>	v3.4.2	<b>Date:</b>	072116
<b>Product:</b>	DS-76xxNI-E1(E2)P Series NVRs		v3.4.21	<b>Page:</b>	1 of 1
<b>Action Required:</b>	None, Information Only				

## ■ Summary

### ● NVR Models Affected:

DS-7604NI-E1/4P	DS-7608NI-E2/8P	DS-7616NI-E2/16P
-----------------	-----------------	------------------

## ■ Compatible IP Cameras

IP Camera Model	IP Camera Firmware
2xx2 Series	v5.3.0_151016
40xx,41xx,42xx,43xx,6412FWD Series	v5.3.4_150812
1x02,2xx0,2x14 Series	v5.3.0_151016
4026FWD, 6026FHWD, iDS-6xxx Series	v5.3.4_150812
4xx5 Series	v5.3.4_150812
2x22FWD, 2x42FWD Series	v5.3.6_151105
IPD DF Series	v5.3.10_150917
IPD DF Series	v5.3.2_150519
IPD DE Series	v5.3.9_150910
DS-2CD2942F-IS (Fisheye)	v5.3.3_151016
DS-2CD6412FWD-C2	v5.1.7_140904
DS-2CD63XXF (Fisheye)	v5.0.9_141009

## ■ Firmware v3.4.21

### ● Changes

Changes	Google has abandoned SSL recently, which resulted in failure when using our devices to send Gmail e-mails. Added TLS feature to overcome this change by Google.
---------	---

## ■ Firmware v3.4.2

### ● Changes

Changes	Changed "EZVIZ Cloud P2P" to "Hik Cloud P2P."
	Changed "dev.ezviz7.com" to "dev.hik-connect.com."
	Removed the update button from the Web interface (System > System Settings interface).
	Changed the boot up screen picture (changed "Copying" to "Copyright").
Bug Fixes	Fixed the bug that can't detect Mac Web Plugin.
	Fixed the Web component for Windows security issue.